

Report No: DEA/01283/3/ISCA

**ASBESTOS SURVEY:**  
St Cadocs Hospital  
Isca Ward



Surveyed by: \_\_\_\_\_



Survey report by: \_\_\_\_\_



Authorised by: \_\_\_\_\_



**Prepared by:**

Scientifics Ltd  
Environment Group  
500 London Road  
Derby  
DE24 8BQ  
Tel: 01332 264444  
Fax: 01332 263386

**Prepared for:**

Gwent NHS Trust  
Llanfrecha Grange  
Torfaen  
Cwmbran  
NP44 8YN

© Copyright Scientifics Ltd

This document was supplied to Gwent NHS Trust under the terms of a contract. The information contained in it is confidential and shall not be divulged without the permission of Gwent NHS Trust. The document or the information in it shall not be used for any purpose outside the terms of the contract without the express permission of Scientifics Ltd.

Issued by Scientifics Limited, 500 London Road, Derby DE24 8BQ.

## COMMENTS AND RECOMMENDATIONS SUMMARY

The insulation panels behind radiators at multiple locations (see report) and a wall panel in the O/T Kitchen were found to contain amosite. These panels were generally in good order and sealed.

Floor tiles in store room 41 & room 50 were found to contain chrysotile.

Labelling of these materials should be maintained to avoid inadvertent damage.

## TABLE OF CONTENTS

1. INTRODUCTION
2. SITE DESCRIPTION
3. SAMPLING STRATEGY
4. SURVEY STRATEGY
5. BULK ANALYSIS METHOD
6. REPORT STRATEGY DEFINITIONS

## APPENDICES

APPENDIX A: REPORT SHEETS

APPENDIX B: DRAWINGS

## 1. INTRODUCTION

Instructions were received from Steve Knight on behalf of Gwent Healthcare to carry out an asbestos survey on the property known as St Cadoc's Hospital, Isca Ward, , , , . This survey was carried out 20th March 2001.

The scope of works was to carry out a full asbestos location survey on the premises as outlined by the client. The extent and type of asbestos based materials on site was to be defined.

## 2. SITE DESCRIPTION

Isca Ward is a single storey block with a flat roof adjoining Augustus Ward and the Day Unit.

### 3. SAMPLING STRATEGY FOR ASBESTOS MATERIAL (HEALTH & SAFETY POLICY)

The object of carrying out sampling was to identify the nature and extent of any visible asbestos material.

All samples were collected in self seal bags where appropriate, and where practicable a label was left on the site adjacent to the sample location. This label indicates the sample number for cross reference to this report. Care was taken to prevent cross-contamination of samples.

All sampling was undertaken causing the minimum possible nuisance and potential risk to the health of the occupants and visitors of the building.

As required under the Control of Asbestos at Work Regulations 1987 as amended by the Control of Asbestos at Work (Amendment) Regulations 1992 and 1998, dust release in sampling must be reduced to as low as is reasonably practicable and an assessment in respect of likely dust release will dictate the need for precautionary measures. This includes the isolation of the sampling area, wetting of the material to suppress dust release, an appropriate cleaning process and use of personal protective equipment. After sampling, any broken material was sealed with PCL cloth tape. All samples were double sealed in polythene bags. Sampling did not impair the structural integrity of the building or plant.

#### 4. ASBESTOS SURVEY STRATEGY

Knowledge, training and experience of the common application of materials that may contain asbestos form the basis of the sampling strategy adopted for this survey. The building was surveyed visually in a systematic manner following documented in-house procedures for materials suspected of containing asbestos.

A strategy has been established to keep to a minimum the number of bulk samples taken for analysis and therefore minimise the cost of the survey. The strategy employed is a combination of a visual inspection and sampling of bulk materials.

During the survey, where a material was suspected to contain asbestos, a bulk sample was taken for analysis. In areas where there were substantial quantities of visually uniform materials, a small number of samples were taken as being representative of the whole area. Therefore, where a sample is identified as containing asbestos, visually similar materials in the same area must be assumed to also contain asbestos.

Where the survey reports a material as NON-ASBESTOS by visual inspection and with no analysis of samples (e.g. recently lagged pipework covered with metal cladding) then the client should exercise caution in interpreting the results. It is IMPORTANT to stress that in such circumstances, there may be residues of asbestos trapped under the newly applied lagging (e.g. from previous asbestos removal carried out in the past).

It is not usually practicable to detect such residues until major disturbances of the material take place within the scope of a destructive survey. Therefore Scientifics Ltd cannot accept liability for the detection of such residues in this survey. If the client undertakes major alterations in a specific area where it may be possible that residual asbestos may be found, then it is recommended that further investigation of the specific area be carried out before the start of work.

Where "NO ACCESS" is used, it indicates that the area specified was not accessible at the time of the survey. The client is to be alerted to the possibility of there being asbestos materials in the

area. This may therefore require further investigation. Only those areas defined are covered in this report. Those areas not identified should be considered as not accessed for the purpose of this survey.

## 5. METHODS OF BULK SAMPLE ANALYSIS

Samples were examined for the presence of asbestiform fibres using polarised light microscopy (PLM) and dispersion staining techniques in accordance with documented in-house procedures based on Health & Safety Executive Publication MDHS 77, 'Asbestos in Bulk Materials'.

Identification of asbestos fibres was based on the following analytical procedure:

- A) A preliminary visual examination of the whole of the bulk sample was made to assess the sample type and the required sample treatment (if any) : where possible a representative sub-sample treatment was taken at this stage;
- B) Sample treatment was undertaken (if required) to release or isolate fibres;
- C) A detailed and thorough search under the microscope was made to classify the fibre types present;
- D) Representative fibres were mounted in appropriate RI liquids on microscope slides;
- E) The different fibrous components were identified using PLM.

## 6. REPORT STRATEGY DEFINITIONS

All asbestos containing materials identified on the site have been incorporated into a Risk Assessment Priority Rating System which will allow the client the opportunity to plan any requirements for removal, remedial action and costings.

Implementation of the system will ensure:

A safe working environment is maintained on site with respect to all asbestos materials identified.

Compliance with the appropriate Health & Safety Legislation

A Priority Rating will be assigned to each asbestos element identified on the sites surveyed. Non-asbestos elements will not be assigned a priority rating. The priority rating is based on a combined assessment of the condition, friability and location of the asbestos element.

### 6.1 Assessment of Condition of Asbestos Elements

**GOOD** - Asbestos elements in good condition are those which are intact, have not been machined or drilled and are in all aspects pristine. Good condition may be achieved in moulded or preformed products when the moulding has not been damaged cracked or broken. Pipework lagging, whole sections and asbestos insulating boarding, fully sealed would also be assigned to a good category.

**FAIR** - Asbestos elements in fair condition are those that have been machined, indented or cracked but damaged asbestos has not fallen or broken away.

**POOR** - Asbestos elements in poor condition indicate that some asbestos material has been damaged by being broken or shattered with some debris present. This indicates that some asbestos material has become detached from the original bulk of the asbestos element.

## 6.2 Assessment of Damage Potential of Each Asbestos Element

The damage potential of each asbestos element on site will be assessed. This is important as the damage potential relates to the likelihood or possibility of damage occurring to the asbestos. The potential for damage or impact on asbestos materials must be considered in conjunction with the likely building usage of the area in question. Risk of damage will be more likely in areas of constant use in comparison with areas of intermittent use of entry for maintenance inspections or observation of equipment.

LOW - Asbestos materials with a low damage potential are those elements which are difficult to reach or damage due to it being in a location which is not normally accessible, except for the purposes of maintenance, e.g. in a roof space or plant room.

MEDIUM - Asbestos materials with a medium damage potential are those elements where some degree of effort would be required to reach and damage the asbestos, e.g. using a ladder or standing on a chair.

HIGH - Asbestos materials with a high damage potential are those elements which are within normal reach to touch or damage.

## 6.3 Assessment of Friability of Each Asbestos Element

The degree of friability of each asbestos element is probably the most important category since the softness of the asbestos material largely determines the extent of asbestos fibre release into the adjacent atmosphere.

LOW - Low friability asbestos materials are those where the asbestos fibres are locked within hard materials such as cement, concrete or plastics. In these cases the dangers of fibre release into the atmosphere are negligible providing that the element is not machined, drilled or otherwise worked upon.

MEDIUM - Medium friability asbestos materials are all those elements which are listed in the low category but are in poor condition, including badly weathered asbestos cement. Medium friability materials also include sealed and unsealed asbestos insulating board and bonded asbestos flange gaskets.

HIGH - High friability asbestos materials include all sprayed and lagged asbestos and unbonded asbestos rope materials. Finely divided asbestos insulating board debris contamination would also be classified as a high friability material.

#### **6.4 Assessment of Priority of Each Asbestos Element**

1 - Priority 1 asbestos materials are in a condition or location which requires urgent attention. Priority 1 asbestos materials are usually not suited to any form of containment programme and should be removed or environmentally cleaned as soon as possible. All fallen asbestos debris and surface contaminating materials will always be assigned a priority rating of 1. Any disturbance to priority 1 materials is liable to expose personnel to elevated levels of airborne respirable asbestos fibres and then also is liable to spread the extent of the contamination throughout the rest of the building.

2 - All priority 2 asbestos materials are in a location and/or condition which require some remedial action. The action may be minor repairs to damaged surfaces or encapsulation of all exposed asbestos surfaces. Following completion of remedial works, the priority 2 material should be assigned a priority 3 rating. In the long term it is recommended that all priority 2 materials be removed as soon as resources become available.

3 - Priority 3 asbestos materials are in a condition and/or location which does not give rise to a significant health risk, PROVIDED THE MATERIAL REMAINS UNDISTURBED either by routine maintenance operations or by personnel carrying out their normal daily work activities which could cause impact or surface damage to the material. Priority 3

is only valid if this provision is maintained. Building managers should be aware of any changes in work activities in areas where priority 3 asbestos materials are located. Priority 3 asbestos materials would change to priority 1 materials if it is decided to carry out building works which would require some disturbance of the asbestos material.

All Priority Rating assessments of all asbestos materials found on the site are to be found in the asbestos survey report sheets.

#### **6.5 Computed Risk Assessment of Each Asbestos Element**

0 to 15 (LOW) - Materials with assessment scores between 0 to 15 should be regarded as low risk materials, which will only need removal if serious damage or deterioration is detected in periodic inspections.

16 to 26 (MEDIUM) - There is little likelihood that a release will occur, or if there is an increased likelihood the type of material present will release only very low levels of airborne fibres. The material does not need any immediate work and any removal can be planned within a suitable budget and timescale. In the meantime it should be labelled and subject to re-inspection and re-assessment at suitable periods.

27 to 40 (HIGH) - This is a situation in which there is a high likelihood that friable loose asbestos may be dispersed giving a significant airborne fibre release. Some immediate plans for remedial work are usually required and the area should be isolated from access by adequately trained personnel.



Site ID: DEA/01283/3/ISCA  
 Location ID: 3/194  
 Building: Isca Ward  
 Floor:  
 Room / Area: Dining Room 45  
 Description: Panels behind radiators



Photograph Number: 85

**GENERAL DETAILS**

Last Inspection Date:	19/Apr/2001	Survey Type:	VISUAL
Next Inspection Date:		Lab Reference	01492/3/194
Source Of Info:		Sample Number	3/194
Surveyed	YES		

**ASSESSMENT DETAILS**

Position	INTERNAL (OCCUPIED)	Damage Potential	MEDIUM
Sample Result	AMOSITE	Notifiable	YES
Material	INSULATION BOARD	Action:	MANAGE / LABEL
Amount		Work Status:	MATERIAL TESTED
Condition	GOOD	Priority	3
Surface Treatment	SEALED		
Friability	MEDIUM	Computed Risk Assessment	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

**Site ID:** DEA/01283/3/ISCA  
**Location ID** 3/195  
**Building** Isca Ward  
**Floor**  
**Room / Area** Lounge Room 46  
**Description** Panels behind radiators



Photograph Number: 86

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01495/3/195
<b>Source Of Info:</b>		<b>Sample Number</b>	3/195
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	MEDIUM
<b>Sample Result</b>	AMOSITE	<b>Notifiable</b>	YES
<b>Material</b>	INSULATION BOARD	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	MEDIUM	<b>Computed Risk Assessment</b>	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

**Site ID:** DEA/01283/3/ISCA  
**Location ID:** 3/196  
**Building:** Isca Ward  
**Floor:**  
**Room / Area:** Dormitory C Room 47  
**Description:** Panels behind radiators



Photograph Number: 87

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01492/3/196
<b>Source Of Info:</b>		<b>Sample Number</b>	3/196
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	MEDIUM
<b>Sample Result</b>	AMOSITE	<b>Notifiable</b>	YES
<b>Material</b>	INSULATION BOARD	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	MEDIUM	<b>Computed Risk Assessment</b>	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

Site ID: DEA/01283/3/ISCA  
 Location ID: 3/197  
 Building: Isca Ward  
 Floor:  
 Room / Area: Dormitory B Room 48  
 Description: Panels behind radiators



Photograph Number: 88

**GENERAL DETAILS**

Last Inspection Date:	20/Mar/2001	Survey Type:	VISUAL
Next Inspection Date:		Lab Reference	01492/3/197
Source Of Info:		Sample Number	3/197
Surveyed	YES		

**ASSESSMENT DETAILS**

Position	INTERNAL (OCCUPIED)	Damage Potential	MEDIUM
Sample Result	AMOSITE	Notifiable	YES
Material	INSULATION BOARD	Action:	MANAGE / LABEL
Amount		Work Status:	MATERIAL TESTED
Condition	GOOD	Priority	3
Surface Treatment	SEALED		
Friability	MEDIUM	Computed Risk Assessment	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

Site ID: DEA/01283/3/ISCA  
 Location ID: 3/198  
 Building: Isca Ward  
 Floor:  
 Room / Area: Clinical room 49  
 Description: Panels behind radiators



Photograph Number: 89

**GENERAL DETAILS**

Last Inspection Date:	20/Mar/2001	Survey Type:	VISUAL
Next Inspection Date:		Lab Reference	01492/3/198
Source Of Info:		Sample Number	3/198
Surveyed	YES		

**ASSESSMENT DETAILS**

Position	INTERNAL (OCCUPIED)	Damage Potential	MEDIUM
Sample Result	AMOSITE	Notifiable	YES
Material	INSULATION BOARD	Action:	MANAGE / LABEL
Amount		Work Status:	MATERIAL TESTED
Condition	GOOD	Priority	3
Surface Treatment	SEALED		
Friability	MEDIUM	Computed Risk Assessment	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

Site ID: DEA/01283/3/ISCA  
 Location ID: 3/199  
 Building: Isca Ward  
 Floor:  
 Room / Area: Store Room 50  
 Description: Floor tiles



Photograph Number: 90

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01492/199
<b>Source Of Info:</b>		<b>Sample Number</b>	3/199
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	LOW
<b>Sample Result</b>	CHRYSOTILE	<b>Notifiable</b>	NO
<b>Material</b>	FLOOR TILES	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	LOW	<b>Computed Risk Assessment</b>	9

**COMMENTS & RECOMMENDATIONS**

**Comments**  
**Recommendations**

**Site ID:** DEA/01283/3/ISCA  
**Location ID:** 3/200  
**Building:** Isca Ward  
**Floor:**  
**Room / Area:** Smoking Room 51  
**Description:** Panels behind radiators



Photograph Number: 91

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01492/3/200
<b>Source Of Info:</b>		<b>Sample Number</b>	3/200
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	MEDIUM
<b>Sample Result</b>	AMOSITE	<b>Notifiable</b>	YES
<b>Material</b>	INSULATION BOARD	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	MEDIUM	<b>Computed Risk Assessment</b>	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

**Site ID:** DEA/01283/3/ISCA  
**Location ID:** 3/201  
**Building:** Isca Ward  
**Floor:**  
**Room / Area:** Dormitory Room 54  
**Description:** Panels behind radiators



Photograph Number: 92

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01492/3/201
<b>Source Of Info:</b>		<b>Sample Number</b>	3/201
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	MEDIUM
<b>Sample Result</b>	AMOSITE	<b>Notifiable</b>	YES
<b>Material</b>	INSULATION BOARD	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	MEDIUM	<b>Computed Risk Assessment</b>	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.

**Recommendations**

**Site ID:** DEA/01283/3/ISCA  
**Location ID:** 3/202  
**Building:** Isca Ward  
**Floor:**  
**Room / Area:** Bedroom 56  
**Description:** Panels behind radiators



Photograph Number: 93

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01492/3/202
<b>Source Of Info:</b>		<b>Sample Number</b>	3/202
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	MEDIUM
<b>Sample Result</b>	AMOSITE	<b>Notifiable</b>	YES
<b>Material</b>	INSULATION BOARD	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	MEDIUM	<b>Computed Risk Assessment</b>	22

**COMMENTS & RECOMMENDATIONS**

**Comments** The reveals of the recessed radiator areas are the same material.  
**Recommendations**

Site ID: DEA/01283/3/ISCA  
 Location ID: 3/204  
 Building: Isca Ward  
 Floor:  
 Room / Area: Room 41  
 Description: Floor tiles



Photograph Number: 95

**GENERAL DETAILS**

<b>Last Inspection Date:</b>	20/Mar/2001	<b>Survey Type:</b>	VISUAL
<b>Next Inspection Date:</b>		<b>Lab Reference</b>	01492/3/205
<b>Source Of Info:</b>		<b>Sample Number</b>	3/205
<b>Surveyed</b>	YES		

**ASSESSMENT DETAILS**

<b>Position</b>	INTERNAL (OCCUPIED)	<b>Damage Potential</b>	LOW
<b>Sample Result</b>	CHRYSOTILE	<b>Notifiable</b>	NO
<b>Material</b>	FLOOR TILES	<b>Action:</b>	MANAGE / LABEL
<b>Amount</b>		<b>Work Status:</b>	MATERIAL TESTED
<b>Condition</b>	GOOD	<b>Priority</b>	3
<b>Surface Treatment</b>	SEALED		
<b>Friability</b>	LOW	<b>Computed Risk Assessment</b>	9

**COMMENTS & RECOMMENDATIONS**

**Comments**  
**Recommendations**

Site ID: DEA/01283/3/ISCA  
 Location ID: 3/205  
 Building: Isca Ward  
 Floor:  
 Room / Area: O/T Room 42  
 Description: Panels behind radiators



Photograph Number: 96

**GENERAL DETAILS**

Last Inspection Date: 20/Mar/2001  
 Next Inspection Date:  
 Source Of Info:  
 Surveyed: YES

Survey Type: VISUAL  
 Lab Reference: 01492/205  
 Sample Number: 3/205

**ASSESSMENT DETAILS**


Position: INTERNAL (OCCUPIED)  
 Sample Result: AMOSITE  
 Material: INSULATION BOARD  
 Amount:  
 Condition: GOOD  
 Surface Treatment: SEALED  
 Friability: MEDIUM

Damage Potential: MEDIUM  
 Notifiable: YES  
 Action: MANAGE / LABEL  
 Work Status: MATERIAL TESTED  
 Priority: 3  
 Computed Risk Assessment: 22

**COMMENTS & RECOMMENDATIONS**

Comments: The reveals of the recessed radiator areas are the same material.  
 Recommendations:

Site ID: DEA/01283/3/ISCA  
 Location ID: 3/206  
 Building: Isca Ward  
 Floor:  
 Room / Area: O/T Kitchen Room 43  
 Description: Wall Panel LHS of fire escape door



Photograph Number: 97

**GENERAL DETAILS**

Last Inspection Date:	20/Mar/2001	Survey Type:	VISUAL
Next Inspection Date:		Lab Reference	01492/3/206
Source Of Info:		Sample Number	3/206
Surveyed	YES		

**ASSESSMENT DETAILS**

Position	INTERNAL (OCCUPIED)	Damage Potential	MEDIUM
Sample Result	AMOSITE	Notifiable	YES
Material	INSULATION BOARD	Action:	MANAGE / LABEL
Amount		Work Status:	MATERIAL TESTED
Condition	GOOD	Priority	3
Surface Treatment	SEALED		
Friability	MEDIUM	Computed Risk Assessment	22

**COMMENTS & RECOMMENDATIONS**

Comments  
 Recommendations





Gwent Healthcare NHS Trust  
Llanfrechfa Grange  
Torfaen  
CWMBRAN  
NP44 8YN

*Scientifics Limited  
Environmental Group  
Swindon Laboratory  
Bristol Street  
Swindon SN1 5ET*

*Tel 01793 499049  
Fax 01793 515646*

fao: Steve Knight, Esq.

o/r: 85500/20/42/1/RAMM(SWA01492/3)

y/r: Order No.CC5868

2 April 2001

**TEST REPORT:**  
**SUSPECTED ASBESTOS FOR IDENTIFICATION**

The samples shown below have been examined by microscope for the presence of asbestiform fibres using polarised light and dispersion staining techniques in accordance with documented in-house procedures based on Health & Safety Executive Publication MDHS 77 *Asbestos in Bulk Materials*.

Job No: SWA01492/3

Date Sampled: 20&21/03/01

Location: St Cadoc's Hospital, Caerleon: **Clinic, Isca Ward**

Lab. Reference	Sample Description	Fibre Type
SWA01492/3/193	Kitchen Room 44, sink/draining board pads	No asbestos found
01492/3/194	Dining Room 435, panels behind radiator(s)*	Amosite
01492/3/195	Lounge Room 46, panels behind radiator(s)*	Amosite
01492/3/196	Dormitory C, Room 47, panels behind radiator(s)*	Amosite
01492/3/197	Dormitory B, Room 48, panels behind radiator(s)*	Amosite
01492/3/198	Clinical Room 49, panels behind radiator(s)*	Amosite
01492/3/199	Clinical Store, Room 50, floor tiles	Chrysotile
01492/3/200	Smoking Room 51, panels behind radiator(s)*	Amosite

Chrysotile = White Asbestos; Amosite = Brown Asbestos; Crocidolite = Blue Asbestos.

Lab. Reference	Sample Description	Fibre Type
SWA01492/3/201	Dormitory Room 54, panels behind radiator(s)*	Amosite
01492/3/202	Bedroom 56, panels behind radiator(s)*	Amosite
01492/3/203	Utility Room 58, sink pads	No fibrous material
01492/3/204	O/T store Room 41, floor tiles	Chrysotile
01492/3/205	O/T Room 42, panels behind radiator(s)*	Amosite
01492/3/206	O/T Kitchen Room 43, wall panel LHS of fire escape door	Amosite
01492/3/207	AS /206, sink pad	No fibrous material

**Analyst:** R Martin **Signature:** 

**Date Analysed:** 30/3/2001

**Comments:** Any opinions and interpretations based on test results are outside the scope of UKAS Accreditation.

Sample /193 contains organic fibre.

The quantity of asbestos in samples /199 & /204 is very small.

\*The reveals of the recessed radiator areas are the same material.



David Gough  
Principal Scientist